

Office of The Executive Engineer, Provl. Divn. PWD B&R Bathinda

Third Floor, Distt. Administrative Complex, Bathinda

Ph. No. 0164-2212878, E-mail ID-xenbtiprovl@gmail.com

APPNENDIX - XI

BUILDING SAFETY
CERTIFICATE

No:- 4659


Dated: 27/08/24

Certified that the existing building..... **Guru Gobind Singh Public School**, ... (name of the building or premises) at....**VPO.....Maluka...Teh...Phul...District...Bathinda** (address) comprise of...**0**...basement (s)**2**...upper floors)owned/ occupied by..... **Guru Gobind Singh Public School** ...(name of the Institution) appears to be safe by visual inspection as verified by the officers concerned of**Executive.....Engineer**.....(Name of Department/ Govt.) on...**22.04.2024**.....(date of inspection) in the presence of.....**Principal**.....(name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy with effect from...**22.04.2024**.....for a period of.....**one**..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The School will ensure that the District Fire Officer Bathinda will issue the Fire safety certificate for the school upto the period of issuance of this certificate.
- 2.
- 3.
- 4.

Valid upto31.03.2025.....by

* Strike out whichever is not applicable.


Executive Engineer,
Provincial Division PWD B&R
Bathinda